



EASA.AP.496
Issue 2

AIR TEAM service, s.r.o.

Procedures demonstrating capability for design EASA finding of compliance – AP496

1 Company name and address:

**AIR TEAM service, s.r.o.
Masarykovo náměstí 354
664 71 Veverská Bítýška
Czechia**

2 Design approval case for which the Company applied for an alternative procedure to DOA:

| Eligibility | |
|--------------------------------|---|
| <i>TC, STC or major repair</i> | <i>Description of case</i> |
| - for STC, as per GM 21A.112B | Changes to sailplanes, powered sailplanes, LSA, VLA, small and large aeroplanes, VLR and small and large rotorcraft related to installation of avionics equipment, special mission equipment, electrical systems, cabin interiors and related structures and systems. |

3 Reference of Procedures:

| <i>Reference</i> | <i>Title</i> | <i>Issue/Date</i> |
|------------------|---|----------------------|
| ATS-ADOA-M | Manual of Alternative Procedures to DOA – STC | Issue 2 / 20.06.2022 |

4 Statement of DOATL having checked the procedures

I hereby state technical approval of the procedures referenced above as meeting the requirement of 21A.112B(b).

Name: Pablo ANTÓN JORNET

Signature:

Date: 03.08.2022



EASA.AP.496
Issue 2

AIR TEAM service, s.r.o.

5 Approval:

Name: Robert BOERSMA

Position: Senior DOATL

Signature:



Date of issue: 03.08.2022